

Please install pressure release knob as the photo shown below, fail to install this pressure release will cause sight view glass damage.

